



Hubshell

	A NDS Flange \varnothing	B NDS Center to Flange	C DS Center to Flange	D DS Flange \varnothing
135/142	49mm	35mm	21mm	60mm
148	49mm	39mm	24mm	60mm
157	49mm	43mm	29mm	60mm

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing